

Parts list

Item	Description	Quantity
1	Clamping device	2
2	Hexagon head bolt M6 x 110	4
3	Nut M6	4
4	Lock washer for M6	4
5	Cap screw M5 x 8	4
6	Shim for M5	4
7	Nut M6	4
8	Lock washer for M6	4

Assembly

- Pre-assemble each of the four hexagon head bolts (2) with a nut (3) and a lock washer (4) to a clamping device (1).
- Assemble the shed to the preassembled clamping device using the Cap screws (5) and shims (6).
- Position both clamping devices at the pipe and fix them using the four nuts (7) and the four lock washers (8).

Materials

All parts are made of stainless steel 1.4301.



Operating n

Assembly set for tube assembly

MR/SD 170

Sun shield SD/K 170 or SD/M 170-D

